PATENT ABSTRACTS OF JAPAN

(11)Publication number:

06-225379

(43)Date of publication of application: 12.08.1994

(51)Int.CI.

H04R 1/40 HO4R 3/12

(21)Application number: 05-010123

(71)Applicant: MATSUSHITA ELECTRIC IND CO

LTD

(22)Date of filing:

25.01.1993

(72)Inventor: FURUTA AKIHIRO


TANAKA TSUNEO

(54) DIRECTIONAL SPEAKER DEVICE

(57)Abstract:

PURPOSE: To provide a directional speaker device for not generating strong side lobes even in a frequency band whose wavelength is shorter than the interval of speaker units.

CONSTITUTION: This device is provided with a speaker array 2 in which 8 speaker units 1 are arranged in a line with a fixed interval and the speaker array 3 composed of 7 speaker units 1 arranged parallelly at the positions next to the speaker array 2 so as to be shifted from the positions of the speaker units 1 with the direction of the speaker array 2 as a reference. Thus, the frequency band is widened to the side of a high frequency band.



LEGAL STATUS

[Date of request for examination]

[Date of sending the examiner's decision of rejection]

[Kind of final disposal of application other than the examiner's decision of rejection or application converted registration]

[Date of final disposal for application]

[Patent number]

[Date of registration]

(Number of appeal against examiner's decision of rejection]

[Date of requesting appeal against examiner's decision of rejection]

P:37/47

Searching PAJ


Page 2 of 2


[Date of extinction of right]


Copyright (C); 1998,2000 Japan Patent Office


(5)


特別平6-225379













(6)

特別平6-225379

(図5)




[图6]




(7)

特別平8-225379

[27]




[图8]



(8)

特別平6-225379

[図10]




Page 1 of 4


* NOTICES *

Japan Patent Office is not responsible for any damages caused by the use of this translation.


- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.**** shows the word which can not be translated.
- 3.In the drawings, any words are not translated.

DRAWINGS







相対音圧レベル (48)




[Drawing 4]

Page 2 of 4









[Drawing 6]


Page 3 of 4






[Drawing 8]

Page 4 of 4





[Translation done.]

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
LINES OR MARKS ON ORIGINAL DOCUMENT
REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
OTHER.

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.